Removing AeolianSkinner opus 1289

Aeolian-Skinner
Opus1289
Refurbishment
Progress Report


April 22, 2024

The Church of the Incarnation 209 Madison New York, NY 10016

Timeframe April 4April 26 2024


- Parish Property Management installs protective coverings for pews and windows on Thursday, April 4
- Friday, April 5 scaffolding installed
- Monday, April 8 Casavant checks site for readiness
- Tuesday, April 9 Casavant 70' truck delivers all materials
- Tuesday, April 9 removal of Aeolian-Skinner op. 1289 begins.

Building Scaffolding – April 4, Thursday



Tuesday, April 9, a 70' truck arrives from Canada

Local movers remove Casavant pipe boxes from truck




Casavant subcontractors Robert, Douglas, and Chris survey access at Tiffany doors



Lift being readied to receive pipes and chests from organ chambers

- 2,800 pound capacity lift
- Manually cranked up and down
- Large boxes and chests are lowered to the floor
- Some chests weigh 900 pounds



Boxes are loaded with pipes pulled from the chamber. The boxes are "lifted" down using a mechanical lift.



Being able to put it back together requires attention to detail.

• Labelling is essential as there are thousands of parts and each must be tied back to its original location and function.




Pipes in boxes along the south wall of the nave are prepared and ready for shipping - think "thousands" not hundreds.




- Neatly boxed and protected, all pipes will leave the Church in boxes with lids.
- All packaging and boxing must be completed by April 26 to meet logistics requirements of shipping, customs, and receiving in Canada.



The chancel and console. Note the pedals on the top part of the photo. The console is completely taken apart.



Finally we can see firsthand the chaotic disposition of the existing organ within the chamber. Notice the pipes that are collapsing.



After partial removal of the great, the exposed positive pipes in the chancel become visible.



Notice random old pipes strewn on the floor of the chamber.

Random



The console has been partially disassembled for shipping. The pedalboard is on its side.




Every ivory key has been removed from the console and will be stored here at the Church: Canada strictly prohibits ivory crossing into Canada.



Inside the chamber --both "floors" of the enclosed boxes have been removed. A box would normally have shutters that the organist opens and closes. They have been removed.








Lo and behold – a window (covered by cardboard) is discovered at the back of the swell chamber (35th Street side). This entire wall requires extensive carpentry once organ is gone.





On April 26, everything will be gone. Three façade pipes remain. They too will travel north for refinishing.





Now it is up to us at Incarnation to do some heavy lifting!



Repair roof.



Resurface all chamber surfaces with MDR board to increase sound reflexivity.



Replace all tongue and groove paneling with non vibrating materials.



Sheet rock walls that are currently covered in cardboard.



Install lighting.



Enclose acoustical space with framing to maximize tonal projection.





•We have raised \$655,000 in pledges! Please help us get to our campaign goal of \$800,000.